



Victron Energy B.V.

De Paal 35

1351 JG Almere
The Netherlands

Product: Bi-Directional Battery Inverter

Model:	MultiPlus-II	MultiPlus-II	MultiPlus-II	
48/3000/35-32,		48/5000/70-50,	24/3000/70-32,	
	MultiPlus-II	MultiPlus-II	MultiPlus-II	
	48/3000/35-32 GX	48/5000/70-50 GX	24/3000/70-32 GX	
Rating:				
DC charge:	48VDCnom., 35Amax	48VDCnom., 70Amax	24VDCnom., 70Amax	
DC diagharas	48VDCnom.,	48VDCnom.,	24VDCnom.,	
DC discharge:	75Amax	110Amax	125Amax	
A C disabawas	230V, 11Amax,	230V, 19Amax,	230V, 11Amax,	
AC discharge:	50/60Hz, 1Ph+N+PE	50/60Hz, 1Ph+N+PE	50/60Hz, 1Ph+N+PE	
Pass through cur-	32A	50A	32A	
rent:	JZA	50A	SZA	
Output power	2,5kVA / 2,47kW	4,5kVA / 4,4kW	2,5kVA / 2,47kW	
(Feed in On-Grid):	2,5KVA / 2,47KVV	4,580474,4800	Z,3KVA / Z,47KVV	
Output power	3,0kVA / 2,4kW	5,0kVA / 4,0kW	3,0kVA / 2,4kW	
(Off Grid):	5,0KVA / 2,4KVV	3,0KVA / 4,0KVV	3,0KVA / 2,4KVV	

kiw

Intended use:

Bi-Directional Battery Inverter with an automatic disconnection device with single-phase mains surveillance in accordance with Technical Regulation 3.3.1 Revision 2 18.12.2019 for plants with a single-phase coupling via an inverter to the public mains supply. The automatic disconnection device is an integral part of the aforementioned inverter.

Applied standards and guidelines:

Technical Regulation 3.3.1 Revision 2 18.12.2019

Technical regulation 3.3.1 for battery plants - category A, SA

The safety concept of an aforementioned representative product corresponds at the time of issue of this certificate to the valid safety specifications for the specified use in accordance with regulations.

Limitations:

- -The model MultiPlus-II 48/5000/70-50 has a current limited to 16A.
- -The models comply with the requirements of Category A.
- -The Ramp rate constraint (load ramp rate ramp function) is not implemented. -The minimum adjustable Undervoltage threshold down to 0,78Un. Under that voltage the unit disconnect with-out intentional delay.
- -The maximum adjustable Overvoltage threshold is up to 1,26Un. Above that voltage the unit disconnect without intentional delay.

Report No: 17PP264-24

Certificate No: 20-065-02

Date of issue: 2021-02-17

Gewerbestraße 28 87600 Kaufbeuren Germany Tel. +49 8341 99726-0

Kiwa Primara GmbH

info@primara.net www.kiwa.de



Tanja Rottach Certification Engineer





B1.2 Documentation for category A energy storage facilities

B1.2.1. Identification

Facility	Description of the facility		
Not part of this certificate	Not part of this certificate		
Facility owner name and address	Not part of this Certificate		
Facility owner telelephone no.	Not part of this Certificate		
Facility owner e-mail	Not part of this Certificate		
Inverter - manufacturer	Victron Energy		
Inverter – rated power	Model MultiPlus-II 48/3000/35-32 and MultiPlus-II 48/3000/35-32 GX;		
	3,0kVA / 2,4kW		
	Model MultiPlus-II 48/5000/70-50 and MultiPlus-II 48/5000/70-50 GX;		
	5,0kVA / 4,0kW		
	Model MultiPlus-II 24/3000/70-32 and MultiPlus-II 24/3000/70-32 GX;		
	3,0kVA / 2,4kW		
Storage medium – manufacturer	-		
Storage medium – model no.	-		
Storage medium – useable energy storage capacity [kWh]	-		
	I		

B122 Normal operation

B1.2.2. Normal operation	
Can the facility be started and operate continuously within the normal operation range, restricted only by protective settings, c.f. requirements in section 7?	Yes ⊠ No □
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	



B1.2.3. Tolerance of frequency deviations

D1.2.6. Folciance of frequency deviations		
Will the energy storage facility remain connected to the public electricity supply grid during frequency deviations as specified in section 4?		
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH		
	<u> </u>	
B1.2.4. Start-up and reconnection of a power-generating plant	1	
Does start-up and automatic reclosing occur after three minutes following voltage and frequency coming within the areas specified in section 4.3.1?	Yes ⊠ No □	
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH		
B1.2.5. Power quality		
For each power quality parameter, please state how the result was achieved.		
Tor each power quality parameter, prease state now the result was demeved.		
B1.2.5.1. Rapid voltage changes		
Does the energy storage facility comply with the rapid voltage changes threshold specified in section 5.1.1.3?	Yes ⊠ No □	
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH		
B1.2.5.2. DC content		
Does DC content at normal operation exceed 0.5% of rated current?	Yes ☐ No ⊠	
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH		



B1.2.5.3. Current imbalance

B1.2.5.3. Current impalance	
Does the current imbalance at normal operation exceed 16 A?	
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	
If the facility is made up of single-phase energy storage units, have measures been taken to ensure that the above threshold is not exceeded?	Yes ⊠ No □
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	
B1.2.5.4. Flicker	
Is the flicker contribution for the entire facility below the threshold specified in section 5.1.1.4? Only the information for the tested unit is available, not for the whole facility. The limits depend on the number of energy storage facilities.	Yes 🗌 No 🗍
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	
B1.2.5.5. Harmonics	
Are all harmonics for the entire facility below the thresholds specified in section 5.1.1.5? Only the information for the tested unit is available, not for the whole facility. The limits depend on the SCR.	Yes
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	
B1.2.5.6. Interharmonics This part must only be filled in for energy storage facilities larger than 50 kW.	
Are all interharmonics for the entire facility below the threshold specified in section 5.1.1.6? Only the information for the tested unit is available, not for the whole facility. The limits depend on the SCR.	Yes No
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	



B1.2.5.7. Disturbances in the 2-9 kHz range

This part must only be filled in for energy storage facilities larger than 50 kW.

The part mast only so this and in tor energy storage rashings and got and out kith	
Is the emission of disturbances with frequencies in the 2-9 kHz range lower than 0.2% of the rated current I_n as required in section 5.1.1.7? Only the information for the tested unit is available, not for the whole facility. The limits depend on the SCR.	Yes No
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	
B1.2.6. Control functions	
B1.2.6.1. Active power control	
B.1.2.6.1.1. Frequency response at overfrequency	<u> </u>
Is the energy storage facility equipped with a frequency response function in case of overfrequency? Only the information for the tested unit is available, not for the whole facility.	Yes ⊠ No □
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	
B.1.2.6.1.2. Absolute power constraint	
Is the energy storage facility equipped with an absolute power constraint function? Only the information for the tested unit is available, not for the whole facility.	Yes ⊠ No □
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	
B.1.2.6.1.3. Ramp rate constraint function	
Is the energy storage facility equipped with a ramp rate constraint function? Only the information for the tested unit is available, not for the whole facility.	Yes ☐ No ⊠
Where to find documentation that this requirement has been met? This requirement is no met.	



B1.2.6.2. Reactive power control

B.1.2.6.2.1. Work area

D.1.2.0.2.1. Work area	
Can the energy storage facility supply reactive power at P_n and varying operating voltages, as specified in section 6.3? Only the information for the tested unit is available, not for the whole facility.	
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	
Can the energy storage facility supply reactive power at varying active power as specified in section 6.3? Only the information for the tested unit is available, not for the whole facility.	Yes ⊠ No □
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	
B.1.2.6.2.2. Power factor control	
Is the energy storage facility equipped with a power factor control function as specified in sections 6.3.2 and 6.3.2.1? Only the information for the tested unit is available, not for the whole facility.	Yes ⊠ No □
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	
B.1.2.6.2.3. Automatic power factor control	
Is the energy storage facility equipped with an automatic power factor control as specified in section 6.3.4 and 6.3.4.1? Only the information for the tested unit is available, not for the whole facility.	Yes ⊠ No □
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	
B.1.2.6.2.4. Q control	
Is the energy storage facility equipped with Q control function as specified in section 6.3.1 and 6.3.1.1? Only the information for the tested unit is available, not for the whole facility.	Yes ⊠ No □
Where to find documentation that this requirement has been met? Test report 17PP264-24 from Kiwa Primara GmbH	



B1.2.7. Protection against electricity system faults

B1.2.7.1. Relay settings

The table below lists default values for relay settings. If default values deviate from the values specified in section 7.2.1, documentation must be provided to ensure that relay settings can be set to the correct values upon commissioning.

Protection function	Sym- bol	Settin	g	Trip tim	е
Overvoltage (step 2)	U _{>>}	264,50	V	200	ms
Overvoltage (step 1)	U>	253,00	V	60	s
Undervoltage (step 1)	U _{<}	195,50	V	50	S
Undervoltage (step 2)	U _{<<}	184,00	V	200	ms
Overfrequency	f _{>}	51,50	Hz	200	ms
Underfrequency	<i>f</i> <	47,50	Hz	200	ms
Frequency change	df/dt	N/A	Hz/s	N/A	ms

B1.2.8. Signature

Date	Not part of this certificate	
Company	Not part of this certificate	
Person responsible for commissioning	Not part of this certificate	
Signature (person responsible for commissioning)	Not part of this certificate	
Facility owner	Not part of this certificate	
Signature (facility owner)	Not part of this certificate	